



EARLE O. BROWN, JR.
(Member of LCOC and LZOC)
229 Robinhood Lane
McMurray, PA 15317
Phone (724) 941-4567
Fax (724) 942-1940

NOS/NEW 1969-71 CONTINENTAL MARK III PARTS
(Genuine Lincoln/FoMoCo/Motorcraft/Autolite Parts)

NO CHARGE FOR PACKING OR SHIPPING (48 States)

Parking Light Lenses, 1969, pair	\$300.00
Parking Light Lenses, 1970-71, pair	\$200.00
Parking Light Bezels, 1969-71, pair	\$200.00
Headlight Vacuum Motors, 1969-71, each	Inquire
Grille Assembly (Shell, C-D-E Bars, Emblem, Seal), 1969-71	\$1500.00
Grille Bars C-D-E, 1969-71, each bar	\$300.00
Grille Emblem, 1969-71	\$125.00
Grille Rubber Seal, 1969-71	\$45.00
Outside Door Handles, 1969-71, pair	\$250.00
Chrome Trim Behind Front Bumper, Long Pieces, 1969-71, pair	\$200.00
Chrome Trim Behind Front Bumper, Short Pieces, 1969-71, pair	\$100.00
Tail Light Lenses, 1969, pair	\$200.00
Tail Light Lenses, 1970-71, pair	\$150.00
Tail Light Bezels, 1969-71, pair	\$300.00
Backup Light Lenses, 1969-71, pair, specify year	\$150.00
Continental Script for Rear Fenders, 1969-71, pair	\$100.00
Quarter Window Outside Chrome Trim, 1969-71, pair	\$400.00
Trunk Lower Stainless Trim, 1969-71, pair	\$200.00
Trunk Letters, "CONTINENTAL", 1969-71, each letter	\$12.00
Rocker Panel Stainless Trim, Wide Pieces, 1969-71, each	\$300.00
Rocker Panel Stainless Trim, Narrow Pieces, 1969-71, each	\$200.00
Wheel Opening Chrome Trim, 1969-71, each (specify)	\$100.00
Door Edge Guards, 1969-71, pair	\$80.00
Sill Plates, 1970-71, pair	\$400.00
Hub Caps, 1969, each	Inquire
Hub Caps, 1970-71, each	\$250.00
Plastic Centers for 1970-71 Hub Caps, set of 4	\$120.00
Key Blanks, 1969-71, pair	\$30.00
Outside Rear View Mirror, Left Side, 1969-71, specify year	\$400.00
Power Window Gear, 1969-71	\$35.00
Turn Signal/Cruise Control Lever, 1969-71	\$300.00
Weather Strip Between Door Glass and Quarter Window, 1969-71, pair	\$100.00
Rubber Drain Hoses for Rear Deck (in trunk), 1969-71, pair	\$100.00
Radiator Fan Shroud, 1969-71, each	\$300.00
Radiator Cap, 1969-71	\$25.00
Radiator Hoses, One Each Upper and Lower, specify year	\$90.00
Battery Tray, 1969-71	\$125.00
Battery Hold Down, 1969-71	\$15.00
Battery Hold Down Bolts, 1969-71, pair	\$12.00
Front Brake Caliper Repair Kit, 1969-71, pair	\$40.00
Brake Hoses, Front, 1969-71, pair	\$150.00
Brake Hose, Rear, 1969-70 or 1971, specify year, each	\$50.00
Fuel Pump, 1969-71	\$60.00
Engine Compartment Decal Set, specify year	\$40.00

Satisfaction Guaranteed or return parts unused within 30 days in original packaging for full refund.
No other Warranty or Guarantee.

EARLE O. BROWN, JR.
(Member of LCOC and LZOC)
229 Robinhood Lane
McMurray, PA 15317
Phone (724) 941-4567
Fax (724) 942-1940

NOS/NEW 1969-71 CONTINENTAL MARK III PARTS
(Genuine Lincoln/FoMoCo/Motorcraft/Autolite Parts)

NO CHARGE FOR PACKING OR SHIPPING (48 States)

Oil Filter Element, 1969-71	\$10.00
Air Filter Element, 1969-71	\$25.00
Gas Line Filter, 1969-71	\$10.00
Ignition Point Set, 1969-71	\$10.00
Ignition Condenser, 1969-71	\$10.00
Distributor Cap, 1969-71	\$15.00
Distributor Rotor, 1969-71	\$10.00
Distributor Vacuum Advance Chamber, 1969-71	\$40.00
Spark Plugs, Autolite, specify year, set of 8	\$20.00
Spark Plug Wire Set, 1969-71	\$85.00
Carburetor Rebuilding Kit, 1969-71	\$45.00
Windshield Washer Pump/Motor Assembly, 1969-71	\$55.00
Front Motor Mounts, 1969-71, pair	\$250.00
Rear Motor (Transmission) Mount, 1969-71	\$150.00
Universal Joint, 1969-71	\$35.00
Heater Core and Seal, 1969-71	\$250.00
Air Conditioner Compressor Gasket Set, 1969-71	\$35.00
Power Steering Pump Seal and Gasket Set, 1970-71	\$30.00
Front Fenders, 1969-71	Inquire
Rear Quarter Panels, 1969-71	Inquire
Door Skins, 1969-71, pair	Inquire
Literature, NOS Originals:	
Owners Manual, specify year	\$30.00
Shop Manual, 1969 (can be used for 1970-71)	\$150.00
Dealers Reference Manual, 1969 (can be used for 1970-71), reprint	\$35.00
Shop Manual, 1970 (5 volume set)	\$150.00
Wiring Diagram, specify year	\$25.00
Quality Aftermarket Exhaust Components, made like originals, 1969-71:	
"H" Pipe	(will not ship) \$300.00
Front Mufflers, pair	\$200.00
Rear Resonators, pair	\$300.00
Pipes between Muffler and Resonator, pair	\$100.00
Quality Rebuilt Water Pump (no exchange necessary), specify year	\$100.00
New Front Brake Pads and New Rear Brake Shoes (Bendix) 4 wheel set, 1969-71	\$200.00

Satisfaction Guaranteed or return parts unused within 30 days in original packaging for full refund.
No other Warranty or Guarantee.

Join the Lincoln and Continental Owners Club: Send \$36.00 annual dues to LCOC, P.O. Box 1715, Dept. EOB, Maple Grove, MN 55311.

Join the Lincoln Zephyr Owners Club: Send \$35.00 annual dues to LZOC, P.O. Box 733, Dept. EOB, Loleta, CA 95551.